

LIMITED 1-YEAR DEALER WARRANTY

Weyerhaeuser Treater Series™ Lumber With Surface or Pressure Treatment

What is Covered?

When properly stored, surface or pressure treated Treater Series™ lumber (Treater Series Lumber) is warranted by Weyerhaeuser NR Company (Weyerhaeuser) against warp that would otherwise result in the product not being saleable, for a period of 1 year from the date of the original purchase of the product from Weyerhaeuser, or until the product physically leaves the dealer's location, whichever is first.

Definition of Covered Conditions

Warp is defined as a twist or curve that has developed in lumber originally manufactured to be flat and straight. The warp attributes of structural lumber covered by this warranty are:

- Bow: This is warp along the length of the face of lumber.
- Crook, or side bend: This is warp along the length of the edge of lumber
- Twist: This is when the faces of the board are not in the same plane along its length.

This warranty does not cover the performance of Treater Series lumber due to:

- Changes in dimensional size due to shrinking or swelling due to secondary surface or pressure treatments or prolonged exposure to moisture.
- Fire, floods, or man-made or natural disaster.
- Cupping of lumber—warping across the width of the board from edges towards center.
- Uses outside the U.S. and Canada

Note: Warp is not caused by wood fungal decay or rot. Like any wood product, all framing lumber may be at risk for mold, fungal decay or rot when exposed to repeated wetting or high-moisture environments, particularly if not properly ventilated. For this reason, manufacturing, design and use features must ensure Treater Series lumber is protected from such exposure by appropriate finish coverings for wall, floor and ceiling systems. This warranty does not cover mold, fungal decay, or rot.

Secondary Remanufacturing and Treatments

Surface and pressure treatment of Treater Series lumber will not void the terms of this warranty. Remanufacturing processes that include re-planing or in any other way changing the original dimensions of the product will void this warranty. Further, Weyerhaeuser specifically disclaims any performance claims, warranties and guaranties regarding the efficacy of any secondary treatments applied.

What Weyerhaeuser Will Do

For lumber covered by this warranty, Weyerhaeuser will pay for the replacement of the material. Weyerhaeuser's payment will not exceed the original cost and the reasonable cost for removal of existing materials or \$10 per linear foot of affected Treater Series lumber, whichever is less.

What You Must Do

You must notify Weyerhaeuser in writing of any claim under this warranty within 30 days of the discovery of the surface deflection at the following address:

Weyerhaeuser Product Assurance Group
33663 Weyerhaeuser Way South
Federal Way, Washington 98003
253.924.5214 • 253.924.4999 (fax)

Upon request, you must provide Weyerhaeuser with reasonable proof of product identification in the form of a product sample, a photograph of the large identifying stamp on each piece, or dated receipt. A Weyerhaeuser representative must be given the opportunity to inspect the product in question.